

Tractor Condition Info & Validation

FLD Name - KRUSHI CAMI PRACTORS, HINGOLI

FLD Mobile No. - 9850933999

FLD Employee Name & Mobile No. - MR, GAJANAN KALE

Tractor Model - MAHINDRA SSS DI (ARJUN)

Tractor Location & Address - HINGOLI

Negotiated Fixed Price with documents - 4,80,000/-

Manufacturing Year - 2017

Registration Year - 2017

Registration No. - MH 38 B 6713

Original Owner Name - ~~MADHAN~~ PANDITRAO RAMRAO NEVHALB

Original Owner Address - ONDHA, HINGOLI

Rear Tyre Condition - 45%

Rear Tyre (Original/Remould) - ORIGINAL

Hour Meter Reading - NOT WORKING

Battery Status - OK

Loan Status (Clear/Pending) - CLEAR

Lender Bank/NBFC Name - NA

Bank NOC Available (Yes/No) - NA

RC Available (Yes/No) - YES

Insurance Validity Date - EXPIRED


Purchased From (Customer/Financer/Broker) - CUSTOMER

Missing/Damage Part if any - NO

Docs Transfer Days - 25 DAY

Pics Tractor LH, RH, Front, Back, Bank NOC & RC + Insurance

30 Sec Video of Tractor Walk-around


PRASHANTH TRACTORS
AKOLA ROAD, HINGOLI

#16A

0524

Registered Number

Registration Date

Reg. Owner's Name

Son/Wife/Daughter of

Address

Address (Permanent)

Maker's Name

Class of Vehicle

Maker's Class

Wheel-base (mm)

Mon. & Year of Mfg.

Motor Vehicle is

Vehicle-Description/

Type of Body

Original Date of Reg

Certificate Valid Upto

(Certificate of Registration)

ner

signed by Registered Owner)

FORM 23 (See Rule 48)

CERTIFICATE OF REGISTRATION MAHARASHTRA STATE, INDIA

Chassis Number
 Engine Number
 Unladen Weight (Kg.)
 Gross Vehicle Weight (Kg.)
 Colour
 Fuel Used
 Cubic Capacity
 Horse Power (B.H.P.)
 Number of Cylinders
 Seating Capacity
 (Including Driver)

WINHMD00865

WINHMD00865

2350

2350

RED

DIESEL

1500

52

Passenger
 1 (including driver) Person

Axle	Number of Tyres	Tyre Description	Registered Axle Weight (Kg.)
Front			
Rear			
Tandem			
Other			
Additional Trailer Particulars			
Front			
Rear			
Tandem			
Other			
Type of Body			
Unladen Weight (Kg.)			

रखरखाव सूची A&B सिरीज				रखरखाव सूची A&B सिरीज				फ्री सर्विस की सूची					Free Serv
नं.	आइटम		सर्विस अंतराल	नं.	आइटम		सर्विस अंतराल	मरिन का प्रकार	NEO STAR	L-Series	MU-Series	PEM 140D	(After 15" Pe
1	इंजन ऑइल	बदलें	पहले 50 और बाद में हर 100 घंटे में	13	ट्रैक्टर का पार्श्व और क्लैम्प	जाँचें	हर 200 घंटे में						
2	इंजन ऑइल फिल्टर	बदलें											
3	हाइड्रॉलिक ऑइल फिल्टर												
4	गियर आइस									30	50	30	60
5	आगे के एक्सल केस का ऑइल												
6	आगे के एक्सल की घुरी									90	250	100	240
7	एयर बिल्वर एलिमेंट वाइबरी												
8	एयर बिल्वर एलिमेंट सेकेंडरी									180	500	200	480
9	स्प्रूज फिल्टर एलिमेंट									0	240	750	300
10	फ्रेम ब्रेन्ट			20	प्रोपेलर								
11	क्लच			21	इंजन चालू करने का सिस्टम	जाँचें	हर 50 घंटे के बाद	पॉचवी फुल मॉ	300	360	1000	400	
12	ब्रेक			22	क्लच हाउसिंग में पचा हुआ पानी	निकास	सर्विस अंतराल के हिसाब से						



The image shows a Kubota A&B Series tractor with a blue canopy. On top of the canopy is a white table with several smaller tables. The tables contain technical specifications for the tractor. The main table on the left lists dimensions and weights. The table on the right lists engine specifications. The background is a plain, light-colored wall.





MH38B-
6713

Mahindra & Mahindra Ltd. Sector, India

Make	Mahindra		
Model	QR JUN 555 DT		
ATIN/Chassis No.	NNHN00165		
Engine Sr. No.	NNHN00025		
Max. PTO Power, kW (hp)	33.5 (44.9)		
SFC, g/kWh, (g/hph)	201 (187)		
Month & Year of Manufacturing	D	G	